



# SUN PROCESS

## VENDING MATERIALS APPLICATION GUIDE

Prepare the surface to which the vinyl will be applied by removing all residue and making sure it is clean and smooth.

Cut the Su-Pro® vinyl to the required length without removing the liner.

Fill a 32 oz. spray bottle with water and add one tablespoon of Joy dish washing soap.

Spray the solution onto the surface of the vending machine to reduce adhesive tension while positioning the vinyl.

As you align the vinyl along the top of the machine, gradually remove the liner.

After the vinyl is applied, use a squeegee to smooth vinyl from the center outward, firming its position.

Wipe dry.

You now have a beautiful like-new vending machine.

**ISO 9001:2015**

*Sun Process Converting, Inc. is registered to ISO 9001:2015 standards*

### SUN PROCESS CONVERTING, INC.

1660 Kenneth Drive, Mt. Prospect, IL 60056

Toll Free: (800) 323-0697 • In Illinois: (847) 593-0447 • Fax: (847) 593-0115

Website: [www.sunprocess.com](http://www.sunprocess.com) • Email: [sales@sunprocess.com](mailto:sales@sunprocess.com)